

Property Management Inspection Services PMIS Protection with Professional Documentation.

Austin 512-600-3375 Dallas 214-960-4551 S.A. 210-807-8774

6/30/2011 12:55 PM

Inspector: Charles Barnes

CUSTOMER NO.: Bridgeman

St. Address: 217 Oak Knoll Circle

City: Boerne

ST: TX. Zip Code: 78006

Type of Inspection:

Initial Inspection:

Transitional Inspection:

Periodic Inspection:

Picture 1 Street View of Home to Include Driveway/Sidewalks



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Exterior of Property

EXTERIOR			Good	Fair	See Additional	Pictures/Needs Further Evaluation	
	1.	Roof/Trim	\boxtimes				
	2.	Exterior Door					
	3.	Walls-All Around	$\overline{\boxtimes}$				
	4.	Front/Back/Side Door		\boxtimes			
	5.	Porch/Patio/Deck					
	6.	Light Fixtures	\boxtimes			(R)	
	7.	Mail Box	\boxtimes				
	8.	Fences (Front & Rear)	\boxtimes				
P	9.	Driveway		1 TO 1	NSPECT	MOS SERVICES	
4	10.	Lawn-Grass					
	11.	Trees/Touching House	\boxtimes				
	12.	Shrubs and Brushes	\boxtimes				
	13.	Pool					
	14.	Other					

Picture #2 Address



Picture #3 Front View of House (Close Up)



Picture #4 Left Side of House and Yard



Picture #5 Right Side of House and Yard



Picture #6 Rear of House and Yard




Picture #7 Picture of AC Unit



Picture #8 Picture of Fence and Gate



Picture #9 Signs of any pets i.e. Dog House



Exterior Comments: Location was absent of any address markings(see#2). Tenant commented that sprinkler system ceased operation appr. 2 months prior to inspection. Requires further inspection. Right rear fenceline is in need of replacement slats due to broken/missing slats(see#71,72). Tripping hazard in front yard from protruding water pipe towards sidewalk(see#1,67).



PROPERTY MANAGEMENT INSPECTION SERVICES

Interior of Property:

Picture #10 Front Door including casing.



If no safety issues or deficiencies observed NO COMMENTS will be Made.

ENTRY WAY Cood Fair See Additional Pictures/Needs Further Evaluation 1. Visible Address 2. Walls/Paint 3. Floors 4. Front Door 5. Keyless Lock 6. Peephole 7. Light Fixtures 8. Other

Picture #11 Porch/Steps



Picture #12 Entry/Foyer



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Good

Fair

Living Room/Great Room

- 9. Flooring
- 10. Walls/Paint
- 11. Light Fixture
- 12. Blinds/Drapes
- 13. Windows
- 14. Ceiling Fan
- 15. Outlet/Switch Covers
- 16. Other

See Additional Pictures/Needs Further Evaluation



Picture #13 Living Room




Picture #14 Living Room Floor




Picture #15 Living Room Ceiling



Picture #16 Living Room Wall



Picture #17 Living Room Wall



Picture #18 Living Room Wall



Good

Not Applicable/Property does not have separate Dining Room/This Section will go unused.

Fair

Dining Room17. Flooring

18. Walls/Paint 19. Light Fixture

20. Blinds/Drapes

21. Windows

22. Ceiling Fan

23. Outlet/Switch Covers

24. Other


See Additional Pictures/Needs Further Evaluation



Picture #19 Dining Room



Picture #20 Dining Room Floor



Picture #21 Dining Room Ceiling



Picture #22 Dining Room Wall



l	Not Applicable/Dreserts		narata Familio Basi	m/This Costion will	
l	Not Applicable/Property	y does not have se	parate railily Roo	m/ mis section will	go unusea.

Family Room/Den	Good	Fair See Additional Pictures/Needs Further Evaluation
25. Flooring	\boxtimes	
26. Walls/Paint	\boxtimes	
27. Light Fixture	\boxtimes	
28. Blinds/Drapes	\boxtimes	
29. Windows	\boxtimes	
30. Ceiling Fan	\boxtimes	
31. Outlet/Switch Covers	\boxtimes	
32. Other		

Picture #23 Family Room




Picture #24 Family Room Floor



Picture #25 Family Room Ceiling




Picture #26 Family Room Wall



Picture #27 Family Room Wall



Picture #28 Family Room Wall



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Kitchen	Good	Fair	See Additional Pictures/Needs Further Evaluation
15. Flooring		10/1	
16. Walls/Paint			
17. Ceiling		9 1	
18. Light Fixtures			
19. Blinds/Drapes			
20. Kitchen Counter/Back Splash	า 🛛		
21. Sink/Faucet	\boxtimes		®
22. Cabinet Under Sink	\boxtimes		
23. Garbage Disposal			
24. Refrigerator		284	INSPECTION SERVICES
25. Range/Oven	\boxtimes		
26. Dishwasher	\boxtimes		
27. Oven			


Picture #29 Kitchen



Picture # 30 Kitchen Floor



Picture #31 Sink/Faucet/Backsplash



Picture # 32 Inside Cabinet Under Sink



Picture #33 Lower Cabinets



Picture # 34 Upper Cabinets



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Hallway/Stairway

- 28. Flooring
- 29. Walls/Paint
- 30. Light Fixture
- 31. Outlet/Switch Covers
- 32. Other


Good

Fair

See Additional Pictures/Needs Further Evaluation







Picture # 36 Hall Lighting/Ceiling



Master Bedroom	Good	Fair	See Additional Pictures/Needs Further Evaluation
33. Flooring	\boxtimes		
34. Walls/Paint	\boxtimes		
35. Light Fixture	\boxtimes		
36. Blinds/Drapes	\boxtimes		
37. Windows	\boxtimes		
38. Ceiling Fan	\boxtimes		
39. Outlet/Switch Covers	\boxtimes		
40. Other		1	


Picture #37 Master Bedroom




Picture # 38 Ceiling (Fan/Smoke Detector?)



Picture #39 Master Bedroom Floor




Picture # 40 Master Bedroom Wall



Master Bath 41. Flooring 42. Walls/Paint 43. Ceiling/Exhaust 44. Light Fixtures 45. Blinds/Drapes 46. Window 47. Sink/Faucet 48. Cabinet Under Sink 49. Shower/Faucet 50. Tub/Faucet 51. Commode 52. Towel Racks	Good X X X X X X X X X X X X X X X X X X	Fair	See Additional Pictures/Needs Further Evaluation
52. Towel Racks 53. Other		18	

Picture #41 Master Bathroom




Picture # 42 Master Bathroom Floor



PROPERTY MANAGEMENT INSPECTION SERVICES

Picture #43 Sink and Faucet



Picture # 44 Inside Cabinet Under Sink



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Not Applicable/Property does not have a 2nd Bedroom/This Section will go unused.

See Additional Pictures/Needs Further Evaluation

ures/Ne	eeas Fur	tner Ev	aiuation
\Box			
- 1 1			
=			
=			
	- 4000	10000	607
100			
\boxtimes			tion.

Picture #45 2nd Bedroom Full Shoot

60. Outlet/Switch Covers

61. Other




Picture # 46 Ceiling (Fan/Smoke Detector)



If no safety issues or deficiencies observed NO COMMENTS will be Made.
Not Applicable/Property does not have a 3 rd Bedroom/This Section will go unused.
3rd Bedroom Good Fair See Additional Pictures/Needs Further Evaluation 62. Flooring
Picture #47 3 nd Bedroom Full Shoot Picture # 48 Ceiling (Fan/Smoke Detector)
If no safety issues or deficiencies observed NO COMMENTS will be Made.
Not Applicable/Property does not have a 4 th Bedroom /This Section will go unused.
4th Bedroom Good Fair See Additional Pictures/Needs Further Evaluation 70. Flooring

Picture #49 4th Bedroom Full Shoot



Picture # 50 Ceiling (Fan/Smoke Detector)



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Not Applicable/Property does not have a 2nd Bathroom/This Section will go unused.

Bathroom 78. Flooring 79. Walls/Paint 80. Ceiling/Exhaust 81. Light Fixtures 82. Blinds/Drapes 83. Window 84. Sink/Faucet 85. Cabinet Under Sink 86. Shower/Faucet 87. Tub/Faucet 88. Commode 89. Towel Racks 90. Other	Good S S S S S S S S S S S S S S S S S S	Fair	See Additional	Pictures/Needs I	Further Evaluation

Picture #51 2nd Bathroom Full Shoot



Picture # 52 Bathroom Floor



Picture #53 Sink and Faucets



Picture # 54 Inside Cabinet under Sink



If no safety issues or deficiencies observed NO COMMENTS will be Made. Not Applicable/Property does not have a 3rd or Half Bath/This Section will go unused. 3rd Bath/Half Bath Good Fair See Additional Pictures/Needs Further Evaluation 91. Flooring 92. Walls/Paint 93. Ceiling/Exhaust 94. Light Fixtures 95. Blinds/Drapes 96. Window 97. Sink/Faucet 98. Cabinet Under Sink 99. Shower/Faucet 100.Tub/Faucet 101.Commode 102.Towel Racks 103.Other Picture #55 3nd Bathroom Full Shoot Picture # 56 Bathroom Floor

Picture #57 Sink and Faucets



Picture # 58 Inside Cabinet under Sink



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Not Applicable/Property does not have a Utility Room/This Section will go unused.

Fair

Utility Room

101. Flooring

102. Walls/Paint

103. Washer Connection

104. Light Fixtures

105. Blinds/Drapes

106. Window

107. Other

Good

 \boxtimes

XI XI

 \boxtimes

See Additional Pictures/Needs Further Evaluation





Picture #59 Utility Room



Picture # 60 Washer Connections



If no safety issues or deficiencies observed NO	COMMENTS will be Made.
Not Applicable/Property does not have a Garage or	Carport/This Section will go unused.
Garage 108. Flooring 109. Walls/Paint 110. Light Fixtures 111. Blinds/Drapes 112. Window 113. Garage Door 114. Other	See Additional Pictures/Needs Further Evaluation
Picture #61 Garage	Picture # 62 Garage Floor
If no safety issues or deficiencies observed NO	COMMENTS will be Made.
Miscellaneous Good Fai	ir See Additional Pictures/Needs Further Evaluation
115. Water Heater 116. AC Filter 117. Pets On the Property 118. Missing/Torn Screens 119. Trip Hazards 120. Drainage Issues 121. Other	

Picture #63 Hot Water Heater



Picture # 64 A/C Filter



Picture #65 Pets On the Property



Picture # 66 Missing/Torn Screen





Interior Comments: Tenant commented that upstairs Game Room was unusually warm. Mentioned warm air coming from elec. outlets & cable outlets. Inspector heard rattling coming from air duct. Tenant thought possible duct disconnection in attic had occurred. Requires further inspection. 2nd Bedroom has disconnected smoke alarm due to malfunction. Tenant commented replacement batteries did not provide solution. Requires further inspection.



PROPERTY MANAGEMENT INSPECTION SERVICES

Additional Pictures

Picture #69



Picture # 70



Picture #71



Picture # 72



Comments: Front and rear yards could use further attention due to extreme dryness(see#69). Front door faded/worn from sun and in need of weatherstripping(see#70,76). Right rear fenceline in need of replacement slats(see#71,72).

Picture #73



Picture # 74



Picture #75



Picture # 76



Comments: Dryer vent pushed away from wall exposing hole(see#73). Left rear corner cracked on bottom(see#74). Hairline crack on rear patio in front of door(see#75). Weatherstripping exposing light gap on front door(see#76).



Comments: A/C filters in need of replacement(see#77). Smoke alarm disconnected due to malfunction in 2nd Bedroom(see#78).

Picture #81	Picture # 82
Picture #83	Picture # 84
Comments:	

Picture #85	Picture # 86
Picture #87	Picture # 88
Comments:	

Picture #89	Picture # 90
Picture #91	Picture # 92
Picture #31	Ficture # 52
	TET CONTRACTOR OF THE PROPERTY
Comments:	

Picture #93	Picture # 94
Picture #95	Picture # 96
Comments:	

Picture #97	Picture # 98
Picture #99	Picture # 100
Comments:	