
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No.	Street			City	Zip		Date of Inspection	Number of Pages
707	Red	Leaf	Court	Daly City	940	14	6/25/2007	4
				Premier Te P. O. Box 2 Half Moon Bay C	266 CA 94019		Report # : 2 Registration Escrow # :	3270 #: PR2464
Ordered by: Linda Kiehnau 4341 Piedmont Oakland, CA 94				Property Owner and/or Part	y of Interest:	Report sent	to:	
COMPLETE REPOR	T	LIM	ITED REPOR	T SUPPLEMENTA	L REPORT	REINSPECTION	ON REPORT	
GENERAL DESCRIPTION: Single Family Unit in Multi Unit Condo Complex Un-Occupied Inspection Tag Posted: Water Heater Closet								
			. ,	wn on the diagram in accordant the diagram were not inspe		ral Pest Control A	ct. Detached porches,	letached
Subterranean Te			Drywood Tecked, it indica	ermites Fungus / es that there were visible pr	· —	Other Findings le areas. Read the		nspection X checked items.

Diagram Not To Scale



Inspected By: Gabe Pack State License No. FR 36825 Signature:

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 1418 Howe Avenue, Suite 18, Sacramento, California, 95825-3204.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (Rev. 10/01)

Front

Page 2 of inspection report

707	Red Leaf (Court	Daly City	CA	94014	
Address of Pr	operty Inspected		City	State	Zip	
		6/25/07	23270			
Stamp No.		Date of Inspection	Co. Report No.	Escrow N	No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

All pesticides and fungicides must be applied by a state certified applicator (sec. 8555 Business and Professions Code Division 3) and in accordance with the manufacturer's label requirements.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

"NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company."

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

Page 3 of 4 of Standard Inspection Report

707	Red Leaf Court	Daly City	CA 94014
Address of Pi	roperty Inspected	City	State Zip
	6/25/07	23270	
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.

" This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection.

SECTION I CONTAINS ITEMS WHERE THERE IS VISIBLE EVIDENCE OF ACTIVE INFESTATION, INFECTION, OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OF INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE THE INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

NOTE: This Wood Destroying Pest and Organisms Report DOES NOT INCLUDE MOLD or any mold-like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold-like conditions, please contact the appropriate mold professional.

NOTE: AREAS OVER 11' ARE NOT INSPECTED ON AN ORIGINAL TERMITE REPORT. NO OPINION IS RENDERED IN THESE AREAS. IF THE HOMEOWNER OR INTERESTED PARTY EXPRESS INTEREST IN HAVING THESE AREAS INSPECTED, WE WILL DO SO FOR AN ADDITIONAL CHARGE.

9. DECKS - PATIOS:

09A - FINDING - The rear deck was not water tested.

RECOMMENDATION - Homeowner to contact the proper trade for evaluation as needed. SECTION II ITEM.

09B - FINDING - Storage door base de-laminating.

RECOMMENDATION - Homeowner to have sealed. SECTION II ITEM.

09C - FINDING - The water heater is not properly blocked or strapped.

RECOMMENDATION - Set proper blocking and proper safety strap to secure. SECTION II ITEM.

09D - FINDING - Stains are noted storage closets.
RECOMMENDATION - Homeowner to contact proper trade for evaluation. SECTION II ITEM.

10. OTHER - INTERIOR:

10A - FINDING - The dwellings bathrooms showed no outward evidence of infestation at the time of inspection. RECOMMENDATION - Homeowner to keep the floors water free, enclosures well sealed, and toilets secured. SECTION II ITEM.

11. OTHER - EXTERIOR:

11A - FINDING - The adjoining units, decks, stairs and exterior was not inspected. No opinion is rendered in this area.

RECOMMENDATION - Unknown further inspection is recommended. UNKNOWN - FURTHER INSPECTION RECOMMENDED.

CERTIFICATION REGARDING TERMITES, FUNGUS AND DRY ROT: This is to certify that the above property was inspected on 6/25/2007 in accordance with the Structural Pest Control Act and rules and regulations adopted pursuant thereto, and that no evidence of active infestation or infection was found.

IF DURING THE COURSE OF REPAIRS ON ITEMS 09A, 09B, 09C, 09D, 10A, 11A DAMAGE OR INFESTATION EXTENDS INTO NOTE: INACCESSIBLE AREAS, A SUPPLEMENTAL INSPECTION AND REPORT WILL BE ISSUED OUTLINING ANY FINDINGS, RECOMMENDATIONS, AND ADDITIONAL COSTS.

"Thank you for selecting our company to perform a structural pest control inspection on your property. Our inspectors have determined that your property will benefit from the safe application of a chemical commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals

Page 4 of 4 of Standard Inspection Report

707	Red Leaf Court	Daly City	CA 94014
Address of Pro	perty Inspected	City	State Zip
	6/25/07	23270	
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.

to such property. Please take a few moments to read and become familiar with the content.

State Law requires that you be given the following information:

""CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized."

""If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center (800-876-4766) and your pest control company immediately."

For further information contact any of the following:

Premier Termite - 650-726-7756

County Health Department - 650-573-2222

County Poison Control Center - 800-876-4766

County Agricultural Commissioner - 650-363-4700

Structural Pest Control Board - 800-737-8188 1418 Howe Ave Suite 18 Sacramento CA 95825

FOR LINOLEUM, CARPETING, WOOD, LAMINATE, OR TILE SAMPLES, PLEASE VISIT OUR SHOWROOM (FLOORS TO GO) AT 116 NORTH CABRILLO HIGHWAY, HALF MOON BAY, OR CALL US AT (650)726-6386.

P. O. Box 266

Half Moon Bay CA 94019

Tel 650-726-7756 Fax 650-726-6383

AGREEMENT

No work will be performed until a signed copy of this agreement has been received.

Address of P	roperty:	707		Red Lea	af Court					
City:		Daly C	ty							
State/Zip:	_	CA	940	14						
The inspection	n report of the	company da	ted,	6/25/0	7 is incorpo	rated herein by refe	erence as thoug	h fully set forth.		
					amount is due ar	ed below from the 1 d payable within Te				
To guarantee of Ninety (90) period not to	days. We ass	ume no resp s, to use rea	onsibility sonable	for work p	ear from date of o	IPANY AGREES ompletion except fors, to be bound to pour work but to ass	perform this wo	rk for the price	quoted in our co	ost breakdown for a
per month, or grants to The	r portion of any Company a se	month, anr curity intere	ual inter st in the	rvices requirest rate of property to	ested upon comp eighteen percent secure payment by owner, wheth	WNER'S AGENT A letion of work to pa (18%) on account: sum for work and in er suit be filed or no RTIES AGREE	ay a service chass exceeding the rspection fee co	e ten (10) day f	ull payment scl	nedule. The Owner
	ontract price do				ling inspector, sa Inspection Repo	id work will not be rt fees. Circle the it				
or other perso that after a co have paid you To preserve t document ent	on who helps to burt hearing, you ur structural pes heir right to file titled "Prelimina	improve you ar property of t control cor a claim or lie ry Notice." F	ur proper ould be s npany in en agains rime con	ty, but is no sold by a co full if the su st your proportractors and	control company t paid for his or h urt officer and the abcontractor, labour erty, certain clair d laborers for wa	E TO OWNER which contracts to er work or supplies e proceeds of the sa erers or suppliers re nants such as subc ges do not have to p lien against your pro-	, has a right to ale used to satis main unpaid. ontractors or mo provide this noti	enforce a claim sfy the indebted aterial suppliers ce. A Prelimina	against your pr ness. This can are required to	operty. This means happen even if you provide you with a
				T		EMS				
Prefix	Section 1	Section	2 I	Further nspection						
09A 09B 09C 09D 10A		Other Homeo 200. Other Homeo	wner 00 Trade	F/I						
Total:		200.				Grand: 20	00.00			
Property Ow					Date:	Inspected By	:			Date:

INVOICE / STATEMENT

Premier Termite

P. O. Box 266 Half Moon Bay CA 94019 Tel 650-726-7756 Fax 650-726-6383

6/24/07 Date: Report Number: 23270 Invoice Number: 23270

Escrow Number:

Property

Inspected: 707 Red Leaf Court

Daly City, CA 94014

Bill To: BRUCE HUTCHKISS

Description of Service

INSPECTION COMPLETE

PAID VIA CC THANK YOU

Inspection Amount:	\$150.00 \$0.00 \$0.00 \$0.00 \$0.00
Invoice Total:	\$150.00
Payments:	\$150.00

\$0.00

Total Due:

RETAIN THIS COPY FOR YOUR RECORDS

THANK YOU FOR YOUR BUSINESS

CUT HERE CUT HERE CUT HERE

INVOICE / STATEMENT

Premier Termite

P. O. Box 266 Half Moon Bay CA 94019 Tel 650-726-7756 Fax 650-726-6383

Property

Inspected: 707 Red Leaf Court

Daly City, CA 94014

Bill To: BRUCE HUTCHKISS

Description of Service

INSPECTION COMPLETE

PAID VIA CC THANK YOU

6/24/07 Report Number: 23270 Invoice Number: 23270 **Escrow Number:**

Inspection Amount: \$150.00 Contract: \$0.00 Labor/Materials: \$0.00 Miscellaneous: \$0.00 Interest: \$0.00 **Invoice Total:** \$150.00 Payments: \$150.00 Additional Charge: \$0.00

> **Total Due:** \$0.00

RETURN THIS COPY WITH REMITTANCE

THANK YOU FOR YOUR BUSINESS