

Wood Destroying Organisms

Chapter 620-6

GEORGIA STRUCTURAL PEST CONTROL COMMISSION - EXCEPTION FORM II

For pre-construction treatments - This Form may only be completed by the property owner after the closing of a final loan

NOTICE TO PROPERTY OWNERS - DO NOT SIGN THIS DOCUMENT UNTIL YOU HAVE READ AND SIGNED "CONDITIONS GOVERNING THE USE OF THE FORM II". THESE "CONDITIONS" MUST BE CONSIDERED PART OF THIS DOCUMENT. YOU MUST RECEIVE A COPY OF THIS REPORT AND SUPPORTING GRAPH.

CONDITIONS GOVERNING THE USE OF THE FORM II

- 1. The Form II, Exception to the Minimum Treatment Standards, is intended to be used ONLY in situations where it is not possible or practical to meet the minimum treatment standards established by the Georgia Structural Pest Control Commission. For pre-construction treatments this form may only be completed by the property owner after the closing of a final loan.
2. The Form II is not to be used to bypass the minimum treatment standards nor is it to be used to notify any agency of government that wood destroying organism work has been completed.
3. By signing this document the property owner acknowledges that the property identified will not receive a complete minimum treatment. Signing this document does not affect the terms of any guarantee between the property owner and the pest control company.
4. Each "no" must be explained in detail in the area provided on the front of this document as to specifically what areas of the structure do not meet the treatment standards and why it is not possible to meet these treatment standards. Additional space is provided below.
5. All sections of this document must be filled out completely. Failure to comply with this requirement or failure to provide the explanation required in "Condition #4" above will constitute a violation involving misuse of this form and may render it void.

Name of Company BARNES TERMITE + PEST CONTROL
Address of Company 3573 SOUTH CABB DR SAVANNA GA 30080
Owner of Property MRS MOSS
Address of Structure Treated - Note: A separate Form II is required for each additional structure. Reproductions of the Form II for multiple structures is not acceptable.
3391 CALEY MILL LA POWDER SPRINGS GA 30127
Phone Number of Property Owner 7-439-8433

Indicate with a check mark those items that do not meet the minimum treatment standards.

SECTION ONE - TERMITE CONTROL - Check one: Post Construction Pre Construction

Soil Barrier - Note: Items 1-10 pertain to post-construction. Only items #1, 2 and 6 can be used for both post-construction and pre-construction applications.

- Date Job Completed 6-9-03
1. All debris removed YES NO
2. Wooden contacts removed or insulated YES NO
3. Termite tunnels removed YES NO
4. Foundation adequately trenched/rodded and treated YES NO
5. Voids adequately drilled/treated YES NO
6. Ventilation adequate YES NO
7. Earth filled porches adequately drilled/treated YES NO
8. Contiguous slabs adequately drilled/treated YES NO
9. Slabs at/above grade adequately drilled/treated YES NO
10. Monolithic slabs adequately treated YES NO

Non Soil Pesticide, Device, Bait or Baiting System - Note: All items pertain to both post-construction and pre-construction applications.

- Date Job Completed YES NO
1. All debris removed YES NO
2. Wooden contacts removed YES NO
3. Ventilation adequate YES NO
4. Barrier or baiting system installed consistent with label directions Not applicable YES NO

SECTION TWO - POWDER POST BEETLES

- Date Job Completed YES NO
1. Vapor barrier properly installed YES NO
2. Ventilation adequate YES NO

SECTION THREE - WOOD DESTROYING FUNGI

- Date Job Completed YES NO
1. Vapor barrier properly installed YES NO
2. Ventilation adequate YES NO

Explain in detail what areas of the structure do not meet treatment standards and why it is not possible to meet these treatment standards. Also, attach a graph indicating the area(s) that were not treated to minimum standards. Failure to attach a graph and provide a detailed written explanation will void this document. Use other side if necessary.

#2 Siding lower than 6 inches to earth on garage
#4 Home has vents + a new vapor barrier.

Signature of Property Owner [Signature] Date 6-9-03
Signature of DCO [Signature] Date 6-9-03

Note: The DCO must sign this document within 21 days of the signature of the property owner. Failure to do so will render the Form II void.

# OFFICIAL GEORGIA WOOD INFESTATION INSPECTION REPORT DIAGRAM

Address 3391 Caley Mill Lane Pkwy Cr 30127 Date June 12, 2006

This diagram must accompany the Official Georgia Wood Infestation Report if evidence of active or previous infestation has been reported.


A careful visual inspection of readily accessible areas of this property indicates evidence of active or previous infestation as follows:

- A. Visible evidence of wood destroying organisms was observed. No control measures were performed.
- B. Visible evidence of wood destroying organisms was observed. Proper control measures were performed.
- C. Visible evidence of active or previous infestation exists as checked below:  
(NOTE: A written description of the location of the infestation such as floor joist, sill, siding, etc. must be given.)

ACTIVE	PREVIOUS	
<input type="checkbox"/>	<input type="checkbox"/>	SUBTERRANEAN TERMITES _____
<input type="checkbox"/>	<input type="checkbox"/>	POWDER POST BEETLES _____
<input type="checkbox"/>	<input type="checkbox"/>	WOOD BORING BEETLES _____
<input type="checkbox"/>	<input type="checkbox"/>	DRY WOOD TERMITES _____
<input type="checkbox"/>	<input type="checkbox"/>	WOOD DECAYING FUNGUS _____

### DIAGRAM

THIS DIAGRAM MUST SHOW THE LOCATION OF INFESTATION AS NOTED ABOVE AND CONDUCIVE CONDITIONS AS NOTED ON THE OFFICIAL GEORGIA WOOD INFESTATION REPORT.



ALTHOUGH THE SCOPE OF THIS INSPECTION INDICATES THAT IT IS NOT TO BE A REPORT OF ANY DAMAGE WHATSOEVER, IT SHOULD BE EMPHASIZED THAT EVIDENCE OF INFESTATION MAY BE SYNONYMOUS WITH DAMAGE.

### KEYS

CONDUCTIVE CONDITIONS EC - EARTH TO WOOD CONTACT IV - INADEQUATE VENTILATION CD - CELLULOSE DEBRIS IN CRAWL SPACE	ST - SUBTERRANEAN TERMITES PPB - POWDER POST BEETLES WB - WOOD BORING BEETLES DT - DRY WOOD TERMITES F - WOOD DECAYING FUNGUS	CONSTRUCTION TYPE CHECK ALL THAT APPLY <input type="checkbox"/> BASEMENT <input type="checkbox"/> SLAB <input checked="" type="checkbox"/> CRAWL
--	---	--

*Basement Termite & Pest Control Co.*  
COMPANY NAME

\_\_\_\_\_  
SIGNATURE OF DCO